



หนังสือรับรองความมั่นคงแข็งแรงของอาคาร

วันที่ออกหนังสือ 11 เมษายน 2568

เรื่อง รับรองความมั่นคงแข็งแรงของอาคารหลังได้รับผลกระทบจากแผ่นดินไหว

เรียน เจ้าของอาคาร มหาวิทยาลัยอัสสัมชัญ

วันที่เข้าทำการตรวจสอบ 7 เมษายน 2568

ข้าพเจ้า นายณัฐวุฒิ สมิทธิเบญจพล วิศวกรโครงสร้าง ระดับวุฒิวิศวกรโยธาใบอนุญาตประกอบวิชาชีพวิศวกรรมควบคุม เลขที่ วย.2402 บริษัท เอ็น.เอส.พลัส เอ็นจิเนียริง จำกัด ซึ่งสามารถรับรองความมั่นคงแข็งแรงของอาคารได้ตาม ข้อบังคับสภาวิศวกรว่าด้วยหลักเกณฑ์และคุณสมบัติของผู้ประกอบวิชาชีพวิศวกรรมควบคุมแต่ละระดับสาขาวิศวกรรมโยธาพ.ศ. ๒๕๖๖ ได้ทำการพิจารณาตรวจสอบสภาพโครงสร้างอาคาร โดยวิธีพินิจ (Visual Inspection) อ้างอิงแบบสำรวจความเสียหายข้างต้นของโครงสร้างอาคาร หลังจากเหตุการณ์แผ่นดินไหว กรมโยธาธิการและผังเมือง

อาคารหอพักนักศึกษา B QUEEN OF SHEEBA

เลขที่ 88 หมู่ 8 ถนนบางนา-ตราด กม.26 ตำบลบางเสาธง อำเภอบางเสาธง

จังหวัดสมุทรปราการ 10570

ซึ่งได้รับผลกระทบจากแผ่นดินไหว โดยผลการพิจารณาตรวจสอบพบว่าโครงสร้างหลักของอาคารอยู่ในสภาพปกติ ไม่พบความเสียหาย ชำรุดบกพร่อง หรือสิ่งซึ่งบ่งบอกว่าอาคารเป็นอันตราย หรือไม่ปลอดภัยต่อการใช้งาน พบเพียงความเสียหายบางส่วนในส่วนงานสถาปัตยกรรม เช่น ผนัง ฝ้า วัสดุตกแต่ง ซึ่งไม่กระทบต่อโครงสร้าง แต่ควรทำการซ่อมแซมแก้ไขให้อยู่ในสภาพปกติพร้อมใช้งาน

ข้าพเจ้าจึงมีความเห็นว่าสภาพโครงสร้างอาคารดังกล่าวข้างต้น มีความมั่นคงแข็งแรง และสามารถใช้งานได้ตามปกติ ดั้งเดิมเหมือนก่อนเกิดเหตุแผ่นดินไหว

ลงชื่อ

(.....นายณัฐวุฒิ สมิทธิเบญจพล.....)

ตำแหน่งวิศวกรโยธา เลขที่ใบอนุญาต วย.2402

วันที่ 11 เมษายน 2568

หมายเหตุ การตรวจสอบสภาพโครงสร้างด้วยวิธีพินิจ (Visual Inspection) เป็นการสำรวจสภาพทางกายภาพด้วยสายตา และประเมินความเสียหาย หรือผลกระทบต่อโครงสร้างเฉพาะในส่วนที่เข้าถึงได้ และเป็นการรับรองสภาพ ณ วันที่เข้าสำรวจเท่านั้น



บริษัท เอ็น.เอส.พลัส เอ็นจิเนียริง จำกัด

เลขที่ 17 ซอยสุขาภิบาล 2 ซอย 3 แขวงประเวศ เขตประเวศ กรุงเทพฯ 10250

Email: infos.nsplus@gmail.com Tel/Fax: 086-307-5103 ID Line :@nsplus

เลขประจำตัวผู้เสียภาษี 0105551008613 สำนักงานใหญ่

ภาพถ่ายอาคาร





N.S. PLUSENGINEERING CO.,LTD.

17 Sukhaphiban 2 Soi 3 Pragate, Bangkok 10250, Thailand

Email: infos.nsplus@gmail.com Tel/Fax: 0-2115-2223 ID Line :@nsplus

TAX : 0105551008613

Certificate of Structural Integrity

Date of Issuance: April 11, 2025

Subject: Certification of Structural Integrity Following Earthquake Impact

To: Assumption University.

Date of Inspection: April 7, 2025

I, Mr. Nattawut Smithibenjapon, a structural engineer holding a professional civil engineering license (License No. WorYor 2402) from N.S. Plus Engineering Co., Ltd., am authorised to certify the structural integrity of buildings in accordance with the 2023 Regulations of the Council of Engineers, outlining the criteria and qualifications for professional engineers in civil engineering , The method of visual inspection refers to the damage survey of the building's structure after the earthquake event, as referenced by the Department of Public Works and Town & Country Planning.

I have conducted an inspection and assessment of the structural condition of the following buildings which were affected by the earthquake:

Queen of Sheeba Residence Hall

Located at 88 Moo 8 Bang Na-Trad Km. 26 Bangsaothong, Samuthprakarn Thailand 10570

The building, which was affected by the earthquake, was inspected, and the results showed that the main structure of the building is in normal condition. No damage, defects, or signs indicating that the building is hazardous or unsafe for use were found. Only architectural elements such as walls, ceilings, and decorative materials were damaged, which do not affect the building's stability or strength.



Therefore, I am of the opinion that the structural condition of the building mentioned above is stable and strong, and it can be used as usual, just like before the earthquake.

Signed: 

(Mr. Nattavut Smithbenjapol)

Position: Civil Engineer License No.: WorYor.2402

Date: April 7, 2025

Note: The structural condition inspection through visual inspection is a survey of the physical condition by sight, assessing damage or impact on the structure only in areas that are accessible. It serves as a confirmation of the condition as of the date of the inspection only.